

FIELD REPORT

TITLE Stone Harbor Maintenance Dredging
 DATE April 4, 2016
 TO Jill Gougher
 COPY MADN
 FROM BEWI
 PROJECT NO A06772

ADDRESS COWI Marine North America
 20 East Clementon Rd.
 Suite 201N
 Gibbsboro, NJ 08026

TEL 856-248-1200
 FAX 856-248-1206
 WWW cowi-na.com

PAGE 1/6

Project Information

Owner: The Borough of Stone Harbor
Contractor: Severson Environmental Services, Inc.

Daily Site Visit Information

Purpose of Visit: Observation of work in progress

Contractor: Severson Environmental Services, Inc. **Superintendent:** Douglas Pike

Arrival

Time (HHMM): 0600 **Weather:** ☐ Sunny ☒ Clear ☐ Overcast ☐ Rain ☐ Snow

Air Temp (°F): 52 **Wind:** ☒ Light ☐ Moderate ☐ High **Humidity:** ☒ Dry ☐ Moderate ☐ Humid

Departure

Time (HHMM): 1430 **Weather:** ☒ Sunny ☐ Clear ☐ Overcast ☐ Rain ☐ Snow

Air Temp (°F): 58 **Wind:** ☒ Light ☐ Moderate ☐ High **Humidity:** ☒ Dry ☐ Moderate ☐ Humid

Site Locations:

Field Office: **Construction Personnel On Site:** 2-3
Equipment on Site (Standby or Operating): Operational – Office Trailers (x2)
Observations: Sevensons personnel working in trailers.

North Basin: **Construction Personnel On Site:** 0
Equipment on Site (Standby or Operating): N/A
Observations: Marina pile replacement in progress.

De-watering Area: **Construction Personnel On Site:** 6-7
Equipment on Site (Standby or Operating): Demobilization in progress.
Observations: Demobilization in progress.

Actions to be Taken: Cleanup.

Enclosures: Photographs

Photographs



Photograph 1: De-Watering Area – Demobilization in progress. (Looking north)



Photograph 2: De-Watering Area – Demobilization in progress. (Looking west)



Photograph 3: De-Watering Area – Demobilization in progress. (Looking west)



Photograph 4: De-Watering Area – Demobilization in progress. (Looking southwest)



Photograph 5: De-Watering Area – Demobilization in progress. (Looking south)



Photograph 6: Site Entrance – Demobilization in progress. (Looking east)



Photograph 7: De-Watering Area – Marina pile replacement in progress. (Looking south)



Photograph 8: North Basin – Marina pile replacement in progress. (Looking south)