


**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/4/18

Inspected By: 609/619

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water / Leaves / Trash \_\_\_\_\_  
Dirt / Obstruction \_\_\_\_\_ Structural \_\_\_\_\_  
Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin: / How Many: 2  
Labels: Yes / Curb Label: 2 Grate Label: 0  
No \_\_\_\_\_ # Installed: 0  
Notes: North basin is leaking

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320 /  
Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_  
\_\_\_\_\_


State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/4/18

Inspected By: 609/619

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water  Leaves  Trash   
 Dirt  Obstruction \_\_\_\_\_ Structural \_\_\_\_\_  
 Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:  How Many: 4  
 Labels: Yes  Curb Label: 2 Grate Label: 0  
 No \_\_\_\_\_ # Installed: 2  
 Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320   
 Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No  
 Work Order Description: \_\_\_\_\_  
 State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/4/18


Inspected By: 609/619

Location: (Identify street, reference points, and location of problem)




W

Street: 121st & 3rd  
Reference Points: \_\_\_\_\_  
Location of Problem: \_\_\_\_\_



S



N

E

**Type of Problem**

Water   
Dirt

Leaves   
Obstruction \_\_\_\_\_

Trash \_\_\_\_\_  
Structural \_\_\_\_\_

Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:   
Labels: Yes   
No \_\_\_\_\_

How Many: 3  
Curb Label: 1  
# Installed: 6

Grate Label: 2

Notes: \_\_\_\_\_

Recommended Maintenance: \_\_\_\_\_

yearly cleaning

Equipment Needed: 1320   
Other \_\_\_\_\_

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_

Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/4/18

Inspected By: 609/619


Location: ((Identify street, reference points, and location of problem))




W

Street: 1174 3rd  
Reference Points: \_\_\_\_\_  
Location of Problem: \_\_\_\_\_

S



N



E

**Type of Problem**

Water   
Dirt   
Notes: \_\_\_\_\_

Loose   
Obstruction \_\_\_\_\_

Trash   
Structural \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:   
Labels: Yes   
No \_\_\_\_\_

How Many: 3  
Curb Label: 1 Grate Label: 2  
# Installed: 0

Notes: \_\_\_\_\_

Recommended Maintenance: \_\_\_\_\_

yearly cleaning

Equipment Needed: 1320   
Other \_\_\_\_\_

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_


Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/4/18

Inspected By: 609/669

Location: (Identify street, reference points, and location of problem)



Street: 118th & 3rd  
Reference Points: \_\_\_\_\_  
Location of Problem: \_\_\_\_\_

**Type of Problem**

Water  Leaves  Trash   
Dirt  Obstruction  Structural   
Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:  How Many: 5  
Labels: Yes  Curb Label: 2 Grate Label: 2  
No  # installed: 0  
Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320   
Other


Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No  
Work Order Description: \_\_\_\_\_  
State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/4/18

Inspected By: 609/619

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water  Logves \_\_\_\_\_ Trash   
Dirt  Obstruction \_\_\_\_\_ Structural \_\_\_\_\_  
Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:  How Many: 4  
Labels: Yes  Curb Label: 2 Grate Label: 2  
No \_\_\_\_\_ # Installed: 0  
Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320   
Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No \_\_\_\_\_

Work Order Description: \_\_\_\_\_  
\_\_\_\_\_


State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/5/18

Inspected By: 609/619

Location: (Identify street, reference points, and location of problem)



Street: 108th & 3rd  
Reference Points: \_\_\_\_\_  
Location of Problem: \_\_\_\_\_

**Type of Problem**

Water   
Dirt

Leaves   
Obstruction

Trash   
Structural

Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:   
Labels: Yes   
No

How Many: 3  
Curb Labels: 3  
# Installed: 2

Grate Labels: 0

Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320   
Other

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_  
\_\_\_\_\_

State Permit Needed?: \_\_\_\_\_

Work Order Number: \_\_\_\_\_


**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/5/18

Inspected By: 609/619

Location: (Identify street, reference points, and location of problem)

Street: 107th & 3rd  
 Reference Points: \_\_\_\_\_  
 Location of Problem: \_\_\_\_\_



**Type of Problem**

Water  / \_\_\_\_\_  
 Dirt  / \_\_\_\_\_  
 Notes: \_\_\_\_\_

Leaves  / \_\_\_\_\_  
 Obstruction \_\_\_\_\_

Trash  / \_\_\_\_\_  
 Structural \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:  / \_\_\_\_\_

Labels: Yes  / \_\_\_\_\_  
 No \_\_\_\_\_

How Many: 10  
 Curb Label: 4  
 # Installed: 1

Grate Label: 6

Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320  / \_\_\_\_\_  
 Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_





**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/5/18


Inspected By: 609/619

Location: (Identify street, reference points, and location of problem)

Street: 105 & 3rd

Reference Points: \_\_\_\_\_

Location of Problem: \_\_\_\_\_



**Type of Problem**

Water   
Dirt

Leaves   
Obstruction ROCKS

Trash   
Structural

Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:   
Labels: Yes   
No

How Many: 3  
Curb Label: 0 Grate Label: 3  
# Installed: 0

Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320   
Other

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_


Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/6/18

Inspected By: 602/019

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water  Leaves  Trash   
 Dirt  Obstruction Rock Structural   
 Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:  How Many: 6  
 Labels: Yes  Curb Label: 3 Grate Label: 3  
 No  # Installed: 0  
 Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320   
 Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No \_\_\_\_\_

Work Order Description: \_\_\_\_\_  
 \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_







**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/6/18

Inspected By: 602/619

Location: (Identify street, reference points, and location of problem)



Street: 92<sup>nd</sup> 3<sup>rd</sup>  
 Reference Points: \_\_\_\_\_  
 Location of Problem: \_\_\_\_\_

**Type of Problem**

Water  Leaves  Trash   
 Dirt  Obstruction \_\_\_\_\_ Structural   
 Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:  How Many: 8  
 Labels: Yes  Curb Labels: 4  
 No \_\_\_\_\_ # Installed: 0 Grate Labels: 4  
 Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320   
 Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_  
 \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_




**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/17/18

Inspected By: 609, 619

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water ✓      Leaves ✓      Trash \_\_\_\_\_  
 Dirt ✓      Obstruction \_\_\_\_\_      Structural \_\_\_\_\_  
 Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin: ✓      How Many: 8  
 Labels: Yes ✓      Curb Label: 4      Grate Label: 4  
                   No \_\_\_\_\_      # Installed: 0  
 Notes: \_\_\_\_\_

Recommended Maintenance: yearly maint

Equipment Needed: 1320 ✓  
                           Other \_\_\_\_\_

Date: \_\_\_\_\_      Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_      Work Order Number: \_\_\_\_\_




**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/17/18

Inspected By: 609, 619

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water	<input checked="" type="checkbox"/>	Loose	<input checked="" type="checkbox"/>	Trash	<input checked="" type="checkbox"/>
Dirt	<input checked="" type="checkbox"/>	Obstruction	<u>Rocks</u>	Structural	<input type="checkbox"/>
Notes:	_____				

**Maintenance Performed**

Cleaned Catch Basin:	<input checked="" type="checkbox"/>	How Many:	<u>10</u>	Grate Label:	<u>5</u>
Labels:	Yes <input checked="" type="checkbox"/>	Curb Label:	<u>5</u>	# Installed:	<u>0</u>
	No <input type="checkbox"/>				
Notes:	_____				

Recommended Maintenance: second cleaning due to standing water

Equipment Needed: 1320  Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No \_\_\_\_\_

Work Order Description: \_\_\_\_\_


State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/18/18

Inspected By: 609, 619



Location: (Identify street, reference points, and location of problem)



Street: 88<sup>th</sup> & Pennsylvania

Reference Points: \_\_\_\_\_

Location of Problem: \_\_\_\_\_



**Type of Problem**

Water ✓      Leaves ✓      Trash \_\_\_\_\_  
 Dirt ✓      Obstruction \_\_\_\_\_      Structural \_\_\_\_\_  
 Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin: ✓      How Many: 6  
 Labels: Yes ✓      Curb Label: 2      Grate Label: 4  
                   No \_\_\_\_\_      # Installed: 0  
 Notes: \_\_\_\_\_

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320 ✓  
 Other \_\_\_\_\_

Date: \_\_\_\_\_      Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_      Work Order Number: \_\_\_\_\_


**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 9/18/18

Inspected By: 609/619

Location: (Identify street, reference points, and location of problem)

Street: 91<sup>st</sup> & 3<sup>rd</sup>  
 Reference Points: \_\_\_\_\_  
 Location of Problem: \_\_\_\_\_



**Type of Problem**

Water <input checked="" type="checkbox"/>	Leaves _____	Trash _____
Dirt <input checked="" type="checkbox"/>	Obstruction _____	Structural _____
Notes: _____		

**Maintenance Performed**

Cleaned Catch Basin: <input checked="" type="checkbox"/>	How Many: _____
Labels: Yes <input checked="" type="checkbox"/>	Curb Label: _____
No _____	# Installed: _____
Notes: _____	Grate Labels: _____

Recommended Maintenance: yearly cleaning

Equipment Needed: 1320   
 Other \_\_\_\_\_


Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No  
 Work Order Description: \_\_\_\_\_  
 State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 12/18/18

Inspected By: 609, 650

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water  Leaves \_\_\_\_\_ Trash   
 Dirt  Obstruction \_\_\_\_\_ Structural \_\_\_\_\_  
 Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin: \_\_\_\_\_ How Many: 8  
 Labels: Yes  Curb Label: 4 Grate Label: 4  
 No \_\_\_\_\_ # Installed: 0  
 Notes: \_\_\_\_\_

Recommended Maintenance: Yearly cleaning

Equipment Needed: 1320   
 Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No \_\_\_\_\_

Work Order Description: \_\_\_\_\_

State Permit Needed? \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 12/18/18

Inspected By: 609, 650

Location: (Identify street, reference points, and location of problem)




W

Street: 87th & 3rd  
Reference Points: \_\_\_\_\_  
Location of Problem: \_\_\_\_\_

S

N



E



**Type of Problem**

Water   
Dirt   
Notes: \_\_\_\_\_

Leaves   
Obstruction \_\_\_\_\_

Trash   
Structural \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin: \_\_\_\_\_  
Labels: Yes   
No \_\_\_\_\_

How Many: 3  
Curb Labels: 1  
Installed: 0

Grate Labels: 2

Notes: Yearly cleaning

Recommended Maintenance: \_\_\_\_\_

Equipment Needed: 1320   
Other \_\_\_\_\_

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_


Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 12/18/18

Inspected By: 6009, 650

Location: (Identify street, reference points, and location of problem)



<b>Type of Problem</b>			
Water	<input checked="" type="checkbox"/>	Leaves	<input checked="" type="checkbox"/>
Dirt	<input checked="" type="checkbox"/>	Obstruction	<input type="checkbox"/>
Notes:		Trash	<input checked="" type="checkbox"/>
		Structural	<input type="checkbox"/>

<b>Maintenance Performed</b>			
<b>Cleaned Catch Basin:</b>	<input checked="" type="checkbox"/>	<b>How Many:</b>	<input type="checkbox"/>
<b>Labels:</b>	Yes <input checked="" type="checkbox"/>	<b>Curb Label:</b>	<u>0</u>
	No <input type="checkbox"/>	<b># Installed:</b>	<u>0</u>
<b>Notes:</b>		<b>Grate Label:</b>	<u>8</u>

**Recommended Maintenance:** Yearly cleaning

**Equipment Needed:** 1320   
Other

**Date:** \_\_\_\_\_ **Confined Space Permit Needed? Yes/No** \_\_\_\_\_  
**Work Order Description:** \_\_\_\_\_


**State Permit Needed?:** \_\_\_\_\_ **Work Order Number:** \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 12-19-18

Inspected By: 609, 630

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water  Loges  Trash   
 Dirt  Obstruction \_\_\_\_\_ Structural \_\_\_\_\_  
 Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin: \_\_\_\_\_ How Many: 5  
 Labels: Yes  Curb Label: 1 Grate Label: 4  
 No \_\_\_\_\_ # Installed: 0  
 Notes: \_\_\_\_\_

Recommended Maintenance: Yearly cleaning

Equipment Needed: 1320   
 Other \_\_\_\_\_


Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No  
 Work Order Description: \_\_\_\_\_  
 State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 12-19-18

Inspected By: 609, 650

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water ✓ Leaves \_\_\_\_\_ Trash ✓  
 Dirt ✓ Obstruction \_\_\_\_\_ Structural \_\_\_\_\_

Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin: \_\_\_\_\_ How Many: 1  
 Labels: Yes X Curb Label: 0 Grate Label: 1  
 No \_\_\_\_\_ Installed: 0

Notes: \_\_\_\_\_

Recommended Maintenance: Yearly cleaning

Equipment Needed: 1320 X  
 Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_






**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 12-20-18

Inspected By: 609, 650

Location: (Identify street, reference points, and location of problem)



Street: 80th & 3rd  
 Reference Points: \_\_\_\_\_  
 Location of Problem: \_\_\_\_\_

**Type of Problem**

Water X      Leaves X      Trash X  
 Dirt X      Obstruction \_\_\_\_\_      Structural \_\_\_\_\_

Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin: \_\_\_\_\_      How Many: \_\_\_\_\_  
 Labels: Yes \_\_\_\_\_      Curb Label: \_\_\_\_\_      Grate Label: \_\_\_\_\_  
                   No \_\_\_\_\_      @ Installed: 0

Notes: \_\_\_\_\_

Recommended Maintenance: Yearly cleaning

Equipment Needed: 1320 X  
 Other \_\_\_\_\_

Date: \_\_\_\_\_      Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_


State Permit Needed?: \_\_\_\_\_      Work Order Number: \_\_\_\_\_

## DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM

Date: \_\_\_\_\_

Inspected By: \_\_\_\_\_

Location: (Identify street, reference points, and location of problem)



### Type of Problem

Water <input checked="" type="checkbox"/>	Leaves <input checked="" type="checkbox"/>	Trash <input checked="" type="checkbox"/>
Dirt <input checked="" type="checkbox"/>	Obstruction <input checked="" type="checkbox"/>	Structural <input checked="" type="checkbox"/>
Notes: <u>Drain on north side needs patch vent</u>		

### Maintenance Performed

Cleared Catch Basin: <input checked="" type="checkbox"/>	How Many: <u>2</u>	Grate Label: _____
Labels: Yes <input checked="" type="checkbox"/>	Curb Label: <u>2</u>	Installed: _____
No <input type="checkbox"/>		
Notes: _____		

### Recommended Maintenance:

Clean catch Basin

Equipment Needed: 1320

Other: \_\_\_\_\_

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_


Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 8-15-19

Inspected By: 609, 607

Location: (Identify street, reference points, and location of problem)



Street: 99th & Corithian

Reference Points: \_\_\_\_\_

Location of Problem: \_\_\_\_\_

**Type of Problem**

Water   
Dirt

Leaves   
Obstruction \_\_\_\_\_

Trash   
Structural \_\_\_\_\_

Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:  
Labels: Yes   
No \_\_\_\_\_

How Many:  
Curb Label: 2  
Installed: 0

Grate Label: 1

Notes: \_\_\_\_\_

Recommended Maintenance: Yearly cleaning

Equipment Needed: 1320   
Other \_\_\_\_\_

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_


Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 8-19-19

Inspected By: 227/273/67

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water	<input checked="" type="checkbox"/>	Leaves	<input checked="" type="checkbox"/>	Trash	<input checked="" type="checkbox"/>
Dirt	<input checked="" type="checkbox"/>	Obstruction	<input type="checkbox"/>	Structural	<input checked="" type="checkbox"/>
Notes:	<u>North west basin in 3rd Ave across from 122nd 3rd Needs Structural Repair</u>				

**Maintenance Performed**

Cleaned Catch Basin:	<input checked="" type="checkbox"/>	How Many:	<u>45</u>
Labels:	Yes <input checked="" type="checkbox"/>	Curb Label:	<u>1</u>
	No <input type="checkbox"/>	Grate Label:	<u>4</u>
Installed:	<input type="checkbox"/>		

Notes: \_\_\_\_\_

Recommended Maintenance: Clean Catch Basin

Equipment Needed: 1320   
 Other

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_


State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 8-20-19

Inspected By: 227/607

Location: (Identify street, reference points, and location of problem)



Street: 121<sup>st</sup> + 3<sup>rd</sup>

Reference Points: \_\_\_\_\_

Location of Problem: \_\_\_\_\_

**Type of Problem**

Water   
Dirt

Leaves   
Obstruction

Trash   
Structural

Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:   
Labels: Yes   
No

How Many: 3  
Curb Label: 1 Grate Label: 2  
# Installed: \_\_\_\_\_

Notes: \_\_\_\_\_

Recommended Maintenance: \_\_\_\_\_

Clean Catch Basin

Equipment Needed: 1320   
Other \_\_\_\_\_

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_


Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 8-20-14

Inspected By: 227/607

Location: (Identify street, reference points, and location of problem)



Street: 118th + 3rd  
 Reference Points: \_\_\_\_\_  
 Location of Problem: \_\_\_\_\_

**Type of Problem**

Water	<input checked="" type="checkbox"/>	Leaves	<input checked="" type="checkbox"/>	Trash	<input checked="" type="checkbox"/>
Dirt	<input checked="" type="checkbox"/>	Obstruction	<input checked="" type="checkbox"/>	Structural	<input type="checkbox"/>
Notes:	_____				

**Maintenance Performed**

Cleaned Catch Basin:	<input checked="" type="checkbox"/>	How Many:	<u>4</u>	Grate Label:	<u>3</u>
Labels:	Yes <input checked="" type="checkbox"/>	Curb Label:	<u>1</u>	# Installed:	_____
	No <input type="checkbox"/>				

Notes: \_\_\_\_\_

Recommended Maintenance: Clean Catch Basin

Equipment Needed: 1320   
 Other \_\_\_\_\_

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_


Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 8-20-19

Inspected By: 227/607

Location: (Identify street, reference points, and location of problem)



Street: 119<sup>th</sup> + 3<sup>rd</sup> L  
 Reference Points: \_\_\_\_\_  
 Location of Problem: \_\_\_\_\_

**Type of Problem**

Water <input checked="" type="checkbox"/>	Leaves <input checked="" type="checkbox"/>	Traffic <input checked="" type="checkbox"/>
Dirty <input checked="" type="checkbox"/>	Obstruction <input checked="" type="checkbox"/>	Structural <input checked="" type="checkbox"/>
Notes: <u>North east corner needs patch over glass top</u>		

**Maintenance Performed**

Cleaned Catch Basin: <input checked="" type="checkbox"/>	How Many: <u>4</u>	Grate Label: <u>2</u>
Labels: Yes <input checked="" type="checkbox"/>	Curb Label: <u>2</u>	Grate Label: <u>2</u>
No <input type="checkbox"/>	Grate Label: _____	

Recommended Maintenance: cleaned catch basin

Equipment Needed: 1320   
 Other

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_




**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 8-21-19

Inspected By: 227/601

Location: (Identify street, reference points, and location of problem)



Street: 118th + Paradise Drive

Reference Points: \_\_\_\_\_

Location of Problem: \_\_\_\_\_

**Type of Problem**

Water	<input checked="" type="checkbox"/>	Loose	<input checked="" type="checkbox"/>	Trash	<input checked="" type="checkbox"/>
Dirt	<input checked="" type="checkbox"/>	Obstruction	<input checked="" type="checkbox"/>	Structural	<input type="checkbox"/>
Notes:	<u>unable to clean basin at Bay end due to construction vehicles and trailers</u>				

**Maintenance Performed**

Cleaned Catch Basin:	<input checked="" type="checkbox"/>	How Many:	<u>2</u>
Labels:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Curb Label:	<u>1</u>
Notes:	<u>Need to add 1 Curb label</u>		

**Recommended Maintenance:**

Clean Catch Basin

Equipment Needed: 1320   
Other

Date: \_\_\_\_\_

Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_


Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 8-21-19

Inspected By: 227/607

Location: (Identify street, reference points, and location of problem)



**Type of Problem**

Water	<input checked="" type="checkbox"/>	Leaves	<input checked="" type="checkbox"/>	Trash	<input checked="" type="checkbox"/>
Dirt	<input checked="" type="checkbox"/>	Obstruction	<input checked="" type="checkbox"/>	Structural	<input checked="" type="checkbox"/>
Notes:	<u>All 3 basins could use some patch work</u>				

**Maintenance Performed**

Cleaned Catch Basin:	<input checked="" type="checkbox"/>	How Many:	<u>1</u>	Grate Label:	_____
Labels:	Yes <input checked="" type="checkbox"/>	Curb Label:	<u>1</u>	# Installed:	_____
	No _____				
Notes:	<u>Need to add 2 Labels</u>				
	<u>Need to order more</u>				

Recommended Maintenance: Clean Catch Basin

Equipment Needed: 1320   
 Other \_\_\_\_\_


Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No  
 Work Order Description: \_\_\_\_\_  
 State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_

**DRAINAGE MAINTENANCE AND PROBLEM REPORT FORM**

Date: 8-21-19

Inspected By: 227/607

Location: (Identify street, reference points, and location of problem)



Street: 117<sup>th</sup> + 3rd Ave

Reference Points: \_\_\_\_\_

Location of Problem: \_\_\_\_\_

**Type of Problem**

Water	<input checked="" type="checkbox"/>	Loaves	<input checked="" type="checkbox"/>	Trash	<input checked="" type="checkbox"/>
Dirt	<input checked="" type="checkbox"/>	Obstruction	<input checked="" type="checkbox"/>	Structural	<input type="checkbox"/>

Notes: \_\_\_\_\_

**Maintenance Performed**

Cleaned Catch Basin:	<input checked="" type="checkbox"/>	How Many:	<u>2</u>
Labels:	Yes <input checked="" type="checkbox"/>	Curb Label:	_____
	No _____	Installed:	_____
		Grate Label:	<u>2</u>

Notes: \_\_\_\_\_

Recommended Maintenance: Clean Catch Basins

Equipment Needed: 1320   
 Other \_\_\_\_\_

Date: \_\_\_\_\_ Confined Space Permit Needed? Yes/No

Work Order Description: \_\_\_\_\_

State Permit Needed?: \_\_\_\_\_ Work Order Number: \_\_\_\_\_